



BUILDING SAFETY CERTIFICATE

Part 'A' Identification of the Property

1(a) **Complete address of the Property** : SRI SARVAJNA EDUCATION SOCIETY
Nos C A .7 & 8, 14th Cross, 5th Main,
M.R.C.R. Layout, Vijayangara, Bangalore-40

(b) **Boundaries** : East Road,
: West C A Site allotted to GT & TC
: North- Road,
: South- Road,

2) **Area of Land**

Measurements : North to South -250'0"
East of West- 150'0"
Sital Area : 37,500.00 Sft.(3483.86 Smtr.)
Shape of the Site : Rectangle.

3) **Built-Up Area** : Basement floor - 8,027.00 SFt.
Ground floor - 8,027.00 SFt.
First floor - 8,027.00 SFt.
Second floor - 8,027.00 SFt.
Third floor -8,027.00 SFt.
Total Built-up Area: 40,135.00Sft.(3728.664 Smtr.)

4) **Year of Construction.** : 2003

5) **Type/Class of Construction** : Good.

6) **Whether the Building is residential/
Commercial/Industrial/Institutional** : Institutional

Structural Details of the Buildings.

i) Foundation

a) **Whether size stone masonry/RCC
footings/Specify others** : RCC Footings and Size Stone Masonry Foundation.
b) **whether condition is good/requires
repairs.** ; Good

ii) Flooring

a) **whether mosaic/marble/cement concrete
specify if others** : Cement Concrete Flooring.
b) **whether the condition is good/
requires repairs.** : Good

iii) Superstructure

a) **Whether Brick masonry/RCC
columns/specify others.** : RCC Columns and TMB Masonry With Cement Mortar.
b) **whether the condition is good/
requires repairs.** : Good

iv) Lintels

- a) Whether RCC/Stone slabs/Brick arch specify others. : RCC Lintels through out the length of the wall
- b) whether the condition is good/ requires repairs. : Good .

v) Roofing

- a) Whether RCC/stone slabs/Madras terrace/specify others : RCC Roof
- b) whether the condition is good/ requires repairs. : Good .

vi) Doors, Windows and Openings.

- a) Whether Teak/Sal-Mathi/Honne jungle wood/ Steel or specify others. : Honne Wood Doors & M S Windows.
- b) whether the condition of doors and windows are good/requires repairs. : Good .

vii) Plastering.

- a) whether Cement mortar/Mud mortar/ Lime mortar/specify others. : Cement Mortar Plastering
- b) whether the condition is good/ requires repairs. : Good in all Floors,

- viii) Electrical Connections. : Institutional Lighting Connections Provided.
- ix) Compound wall : Provided
- x) Water Supply. : From Own well
- xi) Bore well & Pump set Motor. : Open Well Provided.
- xii) Overhead Tank : Provided.
- xiii) Sump/Pump set motor : Provided
- xiv) Quality of construction : Good.
- xv) W.C.Particulars : Provided from B W S S B

C E R T I F I C A T E

*I have Inspected and Certifying that the Institutional Building of
SRI SARVAJNA EDUCATION SOCIETY
at Nos C A .7 & 8, 14th Cross, 5th Main, M.R.C.R. Layout,
Vijayangara, Bangalore-40, is **Strong, Sound and Stable.**
As for the Present The Building is in good condition and is safe
to run the Institutional activities .*



[Signature]
Executive Engineer
Rajarajeshwari
Kengeri Div
BBMP Bangalore

[Signature]
Signature
Renukaradhya S.
BCC/BL-3.6/E-2008/2008-07